

State of Alaska  
 Department of Fish and Game  
 Nomination for Waters  
 Important to Anadromous Fish

1992  
 Year of Revision

# 16

Anadromous Water Catalog Volume Southeast Region 1

ALASKA DEPT. OF  
 FISH & GAME

USGS Quad Craig D-4

OCT 30 1991

Name of Waterway Staney Creek tributary

REGION II  
 HABITAT DIVISION

Anadromous Water Catalog Number of Waterway

103-90-10310-2005-3020

Change to  Atlas

Catalog

Both

Addition

Deletion

Correction

Name addition:

USGS name \_\_\_\_\_

Local name \_\_\_\_\_

For Office Use

Nomination #	<u>92 106</u>
<u>Richard Reed</u> Regional Supervisor	<u>10/20/91</u> Date
<u>Ed Weins</u>	<u>2/20/92</u>
<u>FI</u> Drafted	<u>1/29/92</u> Date

Species	Date(s) Observed	Spawning	Rearing	Migration
<u>Coho</u>		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
<u>Pink</u>		<input checked="" type="checkbox"/>		

Comments: Provide any clarifying information, including number of fish observed, location of fish survey data, etc.

Information from USFS fishery biologist in conjunction with  
USFS culvert replacement project  
Move pink further up drainage

Attach a copy of a map showing location of mouth and upper points of each species, specific stream reaches identified for spawning or rearing, locations of barriers, such as falls. Attach a copy of the fish survey data, if available.

Name of Observer (please print) Vince Harvey


Date: 10/24/91 Signature: by Donald Q. Couelin

Address: ADFG P.O. Box 667

Petersburg Ak 99833.

Signature of Area Biologist: Donald Q. Couelin





2050400 cont.

M.P. 3.7

A small landslide has washed out 30 feet of the road.

2050500 Road

M.P. 2.85

A 48" and a 36" cmp, provide partial fish passage. 36" cmp inlet is blocked, diverting all flow through the 48" cmp. This is causing scouring around the outlet, and may be causing a velocity barrier to fish. Coho salmon stream. Need to replace existing pipes with a 72" or 84" cmp, with a developed outlet pool.

M.P. 4.95

A 96" cmp, appears to be set at an adversely steep gradeint, possibly creating a velocity barrier. Culvert outlet is starting to scour down. Resident fish stream. Would require exstensive excavation to create an outlet pool. Very steep embankments, difficult site to access.

2051100 Road

M.P. 0.1

A 36" cmp, provides partial fish passage. Culvert outlet has a 6" drop-off. Coho salmon stream. Need to develop pool at culvert outlet with rip-rap. Site is low, and easily accessible.

48"

6/5-8/10

2054 Road

M.P. 0.60

A 60" cmp, provides partial fish passage. Culvert outlet has a 6" drop-off. Coho, pink salmon stream. Would be easy to restore passage with a rock of log weir below the culvert outlet.

105-90-10310-2005

will be lowered  
should be a bridge  
7/18-8/10

M.P. 1.40

A 48" cmp, provides partial fish passage. Culvert outlet has an 8" drop-off. Coho salmon stream. Need to develop a large pool below the outlet, or reset the culvert at a lower grade.

60"

7/18-8/10

2078 Road

M.P. 0.15

A 60"cmp with partial fish passage. Outlet is developing a scour, with an 8" drop. This is a coho stream. Problem may be corrected by developing a pool below the outlet, and armoring the pool with rip-rap.

1