



State of Alaska
Department of Fish and Game
Division of Sport Fish

Fish Survey
Nomination Form
Anadromous Waters Catalog

E

Region: Southeast

USGS Quad: Petersburg C-3

Anadromous Waters Catalog Number of Waterway: 106-44-10072

Name of Waterway: Luna Creek

USGS Name

Local Name

Addition

Deletion

For Office Use

Correction

Backup Information

Nomination #	150299	Fisheries Scientist	Date
Revision Year:	2016	Habitat Operations Manager	Date
Revision to: Atlas	Catalog	AWC Project Biologist	13 Jun 15
Revision Code:	F-1	GIS Analyst	Date

Site Information Survey: SEA14MIT58 Date Observed: 06/12/2014 Legal Desc.: C060S079E24 Latitude Longitude Datum
Site: 10203283 56.66085 -132.90625 WGS8

Station Comments WID 17, no FID

Observation Information

Life History:

Species/LifeStage: coho salmon juvenile

Sampling Method (No. of fish): B (1)

Key To Sample Events

Sample ID: (A) Sample Gear: Minnow Trap
Sample ID: (B) Sample Gear: Minnow Trap

coho salmon juv previously documented

Additional Comments: This information was collected as part of ADF&G's Fish Passage Assessment project. This nomination provides back up information for AWC Stream #106-44-10072, Luna Creek for the presence and rearing of juvenile coho salmon. Beaver grate at inlet and extensive evidence of beaver activity both up and downstream. One coho trapped, others observed downstream.

Name of Observer: Mark Eisenman, Habitat Biologist

Phone: (907) 267-2891 Date Printed: 6/17/2015

Signature: *[Signature]*


Address: Alaska Department of Fish and Game, Sport Fish - Anchorage
333 Raspberry Rd
Anchorage, AK 99518

ALASKA DEPT. OF
FISH & GAME


JUL 10 2015

This certifies that in my best professional judgment and belief the above information is evidence that this waterbody should be included in or deleted from the Anadromous Waters Catalog

Signature of Area Biologist: _____ Date: _____




IMGP1897.JPG
Site Sketch



IMGP9477.JPG
Site ID



IMGP9479.JPG
Outlet



IMGP9480.JPG
In outlet



IMGP9481.JPG
Damage in outlet



IMGP9482.JPG
Looking downstream from
outlet



IMG9483.JPG
Outlet



IMG9484.JPG
Downstream habitat




IMG9485.JPG
Outlet



IMG9486.JPG
From road looking downstream



IMG9487.JPG
Road




IMG9488.JPG
From road looking upstream



IMGP9489.JPG
Inlet



IMGP9490.JPG
Inlet



IMGP9492.JPG
In inlet



IMGP9493.JPG
upstream from inlet



IMGP9494.JPG
Inlet



IMGP9495.JPG
Upstream habitat



IMGP9496.JPG
Upstream habitat



IMGP9497.JPG
Coho



MITKOF HIGHWAY

106-44-10072

10203271

10203283

