



State of Alaska
Department of Fish and Game
Sportfish Division

Nomination Form
Fish Distribution Database

Region USGS Quad
 Fish Distribution Database Number of Waterway
 Name of Waterway USGS Name Local Name
 Addition Deletion Correction Backup Information

		For Office Use	
Nomination #	<u>04 347</u>	<u>[Signature]</u>	<u>2-24-05</u>
Revision Year:	<u>2006</u>	Fisheries Scientist	Date: <u>2/24/05</u>
Revision to:	Atlas <input type="checkbox"/> Catalog <input type="checkbox"/>	<u>[Signature]</u>	<u>12-21-04</u>
	Both <input checked="" type="checkbox"/>	FDP Project Biologist	Date
Revision Code:	<u>A-2</u>	<u>[Signature]</u>	<u>4 18 05</u>
		Drafted	Date

OBSERVATION INFORMATION

Species	Date(s) Observed	Spawning	Rearing	Present	Anadromous
Coho	8/6/2004		100+		<input checked="" type="checkbox"/>
Dolly Varden	8/6/2004		6+		<input type="checkbox"/>
					<input type="checkbox"/>
					<input type="checkbox"/>
					<input type="checkbox"/>

IMPORTANT: Provide all supporting documentation that this water body is important for the spawning, rearing or migration of anadromous fish, including: number of fish and life stages observed; sampling methods, sampling duration and area sampled; copies of field notes; etc. Attach a copy of a map showing location of mouth and observed upper extent of each species, as well as other information such as: specific stream reaches observed as spawning or rearing habitat; locations, types, and heights of any barriers; etc.

Comments: Add tributary stream to Lake Rose Tead inlet with coho rearing. On 8/6/2004 numerous rearing coho were observed in outlet pool of Pasagshak Road crossing, site 13177 & 13178 at milepost 5.6. Several were dip netted out of the outlet pool. A trap set upstream yielded only Dolly Varden. However the set was in rather fast water. While rearing coho were not captured above the road juvenile fish which looked and acted like juvenile coho were observed upstream of the crossing. The culvert is currently perched causing a partial blockage to passage, but will be fixed with ADOT road upgrades. See attached photos, table and field notes for additional detail.

*add new stream 259-41-10010-2010-3005
12/CCR*

ALASKA DEPT. OF FISH & GAME
APR 1 2005

Name of Observer (please print): Edward W. Weiss
 Signature: [Signature] Date: 11/15/04
 Address: Habitat Biologist, ADNR - OHMP
550 W. 7th Avenue, Suite 1420, Anchorage, AK 99501

This certifies that in my best professional judgment and belief the above information is evidence that this waterbody should be included in or deleted from the Fish Distribution Database.

Signature of Area Biologist: _____ Revision 04/03
 Name of Area Biologist (please print): _____

TABLE 1
Pasagshak Road Field Visit Summary

September 13, 2004

Milepost	Point #	Trap In	Trap Out	Catch			T41 Required	Site Inspection Description / Discussion
				Dolly Varden	Coho	other		
2.13	13272	10:07	13:50	7	1		YES	<p>These culverts are in good shape and are passing fish. Rearing coho and Dolly Varden were captured at the culvert inlet. Because of the complexities of designing and installing a new crossing that would not impact the ponded area above it was felt that these culverts would be placed on a lower priority and left as is. The road bed needs to be raised here and it was agreed that the roadside vegetation on the foreslope between the road and ponded area would be retained.</p>
2.45	13265	N/A	N/A	N/A	N/A	N/A	NO	
2.6	13260	N/A	N/A	N/A	N/A	N/A	NO	
2.7	13255	N/A	N/A	N/A	N/A	N/A	NO	
2.75	13254	N/A	N/A	N/A	N/A	N/A	NO	
2.8	20017							
3	13248	N/A	N/A	N/A	N/A	N/A	NO	
3	13249	N/A	N/A	N/A	N/A	N/A	NO	
3	13250	N/A	N/A	N/A	N/A	N/A	NO	
3.05	13242	N/A	N/A	N/A	N/A	N/A	NO	
3.06	13241	N/A	N/A	N/A	N/A	N/A	NO	
3.15	13235	N/A	N/A	N/A	N/A	N/A	NO**	
3.15	13236	N/A	N/A	N/A	N/A	N/A	NO**	
3.3	13229	N/A	N/A	N/A	N/A	N/A	NO	
3.5	20020	N/A	N/A	N/A	N/A	N/A	NO	
3.51	13225	N/A	N/A	N/A	N/A	N/A	NO	
3.6+	13224	N/A	N/A	N/A	N/A	N/A	NO	
3.7	13220	N/A	N/A	N/A	N/A	N/A	NO	
3.8	13217	N/A	N/A	N/A	N/A	N/A	NO	
3.8+	13214	N/A	N/A	N/A	N/A	N/A	NO	

