Brady
Scullen (Wilkey)
F&G

Date: 4 Aug 78

Fish Stream Survey Report

Camp Port Alice Stream Name(ID)# 103-80-026 Possibly Eagle Ce.

Road# 5960, B-Spur, A-Spur Station# 6+14 → 59+00 Unit# _____ RP# _____

Possible New Camp site

Quad Map _____ Section _____ Chick Map _____ Section _____

Fish Present Yes _____ No X

Above Road Crossing _____ _____
Below Road Crossing _____ _____
Within Unit Boundary _____ _____
Below Unit Boundary _____ _____

Species Present/Stage of Development No fish

Type of Fish Habitat

Salmon Spawning Area _____ sq yds Describe _____
Salmon Rearing Area _____ sq yds Describe _____
Other _____ Area _____ sq yds Describe _____

Stream Sketch or Map: Attach supplement if necessary:

Method(s) used to determine presence of fish: Shocker

Date	#Fish	Approx Length	Gear	Length of Time Fished

Is future fish habitat enhancement possible? Yes_____ No X

If yes Describe:

Road and Unit boundary/fish stream intersection(s)
Marked with aluminum metal tags Yes_____ No_____

Fish stream(s) flagged with blue stripe tape Yes_____ No_____

Stream(s) traversed-If so attach traverse notes Yes_____ No_____

Additional parameter information necessary, Yes_____ No_____
If so attached completed fish stream parameter
Data form

Pertinent Wildlife Information:
Deer Sign, Bear Sign

Comments: Stream flows very low, many small streams are dry. It is possible that fish would move into some of the stre at higher water. However, due to slopes, + the elevation they probably do not

Survey Crew Members:

Signature	Date
Steven D Hales	4 Aug 78
Thomas Keating	4 Aug. 78

Report Reviewed By Michael E Rovy (Signature) Forester (Title) 8-4-78 (Date)

Recommendations:

Port Alice
5690 Road
A-Spur & B-Spur

5690 Main Line 6+14 → 59+00
We found streams or dry streambeds at Stations 17+95, 26+31, 29+71, 31+55
— No fish were found in any of them.

A Spur
12+14 Small Stream, 3'-4' wide, 4"-8" deep. Appears to be good fish habitat however no fish were shocked. There is a culvert installed (not a fish culvert)
Recommend no change

16+00 Very small stream, steep above the road, 24" Culvert in place, is not a fish culvert 300' downstream it goes into a sink hole
No fish were shocked — No change is necessary

20+20 Very small mustag drainage - no fish shocked, No fish passage required.

* We checked two streams across the bay from Port Alice. Neither had fish. One is the present water supply for Port Alice
The Loggers want to move the Camp to this Area, to be closer to water supply