cc Fred Zeigler
Mark VonTassel
John Ruopp
Fish & Game

Date: 4/30/79

Fish Stream Survey Report

103-90-030

Stream Name (ID) EAST FORK STANLEY CREEK — STR. #25, NAUKATI TR. ROAD (CULVERT #5)

Camp Halfway house

Road# 5650 Station# _____ Unit# NAUKATI TR. BLOCKADE UNIT RP# _____

Quad Map Craig D-4 Section _____ Chick Map _____ Section _____

Fish Present	Yes	No
	X	
Above Road Crossing	X	
Below Road Crossing	X	
Within Unit Boundary	X	
Below Unit Boundary	X	

Species Present/Stage of Development COHO & CUTTHROAT FR

Type of Fish Habitat

Salmon Spawning Area _____ sq yds Describe _____
Salmon Rearing Area X 265 sq yds Describe GOOD
Other X CUTTHROAT Area _____ 265 sq yds Describe GOOD

Stream Sketch or Map: Attach supplement if necessary:

See supplement.

Method(s) used to determine presence of fish:

Stream#	Date	#Fish	Approx Length	Gear	Length of Time Fished
25	10/23/78	COHO	2"	Shocker	10 min.
		CUT	4½"	"	"

Is future fish habitat enhancement possible? Yes_____ No_____
If yes Describe:

Road and ~~Unit boundary~~/fish stream intersection(s)
Marked with aluminum metal tags Yes X No____
Fish stream(s) flagged with blue stripe tape Yes X No____
Stream(s) traversed-If so attach traverse notes Yes_____ No____
Additional parameter information necessary, Yes_____ No____
If so attached completed fish stream parameter Data form

Pertinent Wildlife Information: Deer sign & beaver activity.

Comments: Considerable blowdown in stream below road, may need recreational lands input, (Mr. Short, Campbell and/or Mr. Barber). Lake is adjacent to main tr. Road - has recreational potential - coho, cutthroat, Dolly Varden

Survey Crew Members:	Signature	Date
JIM GRUBER	James O. Gruber	4/30/79
ROD COREY	Rod Corey	4/30/79

Report Reviewed By Mike Novy (Signature) Forester (Title) 4-3-79 (Date)

Recommendations: See attached sheets

Stream 25 (10/23/78) -

This stream is 4'-5' wide, 10" deep with a rock substrate. One Coho 2" in length was shocked above culvert and one cutthroat 4" in length was shocked below the culvert. The culvert is adequate at this date. The stream was flagged B/W 100' above THE ROAD & 490 ft. BELOW ROAD and tagged below the road. (WIDTH & DEPTH OF STREAM WERE TAKEN DURING HIGH FLOW CONDITIONS)

REFER TO NAUKATI TIE / SUPPLEMENT ROAD CULVERT SURVEY 10/23/79.

RECOMMENDATIONS:

1.) DIRECTIONAL FALLING AND YARDING AWAY FROM STREAM. (Standing Trees)

2.) 48 HOUR CLEAN-UP OF DEBRIS CAUSED BY LOGGING ACTIVITY.

3.) CLEAN-UP OF BLOWDOWN DEBRIS CONCURRENT WITH LOGGING ACTIVITY.

4.) AS STREAM BED IS FAIRLY STABLE BELOW ROAD CROSSING AND THAT STREAM IS MAINLY REARING HABITAT, SOME YARDING OF BLOWDOWN ACROSS STREAM IS PERMISSIBLE IN upper portions

5.) FALL & YARD AWAY FROM LAKE SHORE (CLEAN-UP OF

DEBRIS CAUSED BY LOGGING ACTIVITY
FROM LAKE SHORE.

(6.) MAY NEED INPUT FROM RECREATIONAL LANDS
(SEE MR. SHORT &/OR MR. BARBER)


NAUKITI RD. (TIE)
5650
CULVERT (#58)
STK. #25
490 ft.
END STR HABITAT
LAKE (NAME ?)
HOLMGREN
- MAP NOT TO SCALE -



NAUKATI
STANEY
STANEY CK. RD.
NORTH RD.
NORTH FORK
STANEY
SHAHEEN
FORKS SPUR
PRINCE
ISLAND
5400
5420
5430
5411
5412
5500