State of Alaska
Department of Fish and Game
Nomination for Waters
Important to Anadromous Fish

1990
Year of Revision
90-702

Anadromous Water Catalog Volume REGION II

USGS Quad SELDOVIA C-1

Name of Waterway

Anadromous Water Catalog Number of Waterway
232-30-10350

Change to _____ Atlas
_____ Catalog
✓ Both

Addition ✓

Deletion

Correction

Name addition:

USGS name

Local name

1/25/90
Already in catalog
1990 Nomination
BS

For Office Use

Nomination #

Regional Supervisor — Date

Drafted — Date

Species	Date(s) Observed	Spawning	Rearing	Migration
PINK	9/3/89	✓		

Comments: Provide any clarifying information, including number of fish observed, location of fish survey data, etc.

100 LIVE AND 200 DEAD PINKS OBSERVED IN STREAM & LAGOON. HABITAT DIV. SURVEY

Attach a copy of a map showing location of mouth and upper points of each species, specific stream reaches identified for spawning or rearing, locations of barriers, such as falls. Attach a copy of the fish survey data, if available.

Name of Observer (please print) DOUG HILL

Date: 1/8/90 Signature: Douglas D Hill

Address: HABITAT DIVISION - ADF&G
333 RASPBERRY RD, ANCHORAGE

Signature of Area Biologist:

(T)

FISH HABITAT ASSESSMENT FORM

TAROKA Arm - NW most creek

[1]REGION: [2]PWS [3]KP,CI [4]OBSERVER(S) Doug Hill, Rick Randall

[6]SITE NO. 13-5 [7]AERIAL PHOTO NO. 22,23,24,25 [8]CAT NO. NC

[9]STREAM NAME _____ [10]LAT 59° 37' 19" [11]LONG 150° 09' 80"

[12]DATE 9/3/89 [13]TIME 1305 [14]TIDE: Low slack Flood High slack Ebb

[15]CATALOGED ANADROMOUS STREAM? Y N [16]ANAD. FISH FOUND? Y N

[17]OIL FOUND IN STREAM? Y N [18]OIL FOUND NEAR STREAM (1 MI.)? Y N

[19]OIL SAMPLES TAKEN? Y N [20]ID NOS. RDR/DDH-9/3/89-1238

[21]35 mm PICTURES TAKEN? Y N [22]ROLL NO(S). 89-DDH-35

[23]EXPOSURE NO.	[24]DESCRIPTION
22,23	Pinks Dead in isolated pool / Gulls
15,16	Typical oil found at sample site
17,18	Oil found subsurface - Excavation - otherwise oil-free dry locking Ar
19,21	Typical oil at sample site
20	Location ID photo. Stream site 13-5 in background

[25]VIDEO FOOTAGE TAKEN? Y N [26]CASSETTE NO(S). 89-RDR-001-H-Vide

[27]DESCRIPTION: Video of Sample site - within 1 mile of Stream site NO. 13-5 (sample site to NW of 13-5) (2816-2853)

- Video of general Area ie, Aerial of stream 13-5 (2853-2864)

ANADROMOUS FISH OBSERVATIONS

		PINK	CHUM	RED	KING	COHO	DOLLY		
28	Aerial	100 live 200 DEAD							
29	Ground	/							

30 COMMENTS: 200 Dead pinks in isolated pool

OIL OBSERVATIONS

Approx. 200 yards - line of sporadic splatters (1 per 5') of oil at mid-tide level of boulder cobble beach splatters up to 3" diameter.
- Excavation - 6' square area - surface dry with only a few splotches of oil visible. upon turning rocks over we found a nearly continuous pat of 1/16" to 1/8" thick mousse

EXTENT OF OIL:

	WITHIN STREAM	OUTSIDE STREAM
31 SURFACE COVERAGE		
32 SURFACE THICKNESS	None Observed	1 to 3mm
33 PENETRATION		To 8-10"

34 OIL DISTRIBUTION DIAGRAM (SHOW SAMPLING SITES)



35 PREDOMINANT SUBSTRATE TYPE:

1. Bedrock
2. Boulder
3. Cobble
4. Gravel
5. Sand
6. Mud
7. Other_____

36 COMMENTS: Same sample site as that of stream site # 12-3 (see map on site form 12-3)