5

84-697

State of Alaska
Department of Fish and Game
Public Review Nomination for Waters
Important to Anadromous Species

✓ Addition ____ Deletion

Name of Waterbody (if known): Yatuk Creek

Location: T. 68S, R. 80E, Sec 36

Anadromous Waters Catalog Volume and Number 103-90-10260 5

USGS 1:63,360 Quadrangle Craig D-9 3

or 1:250,000 (if 1:63,360 not available) ____

Species	Date(s) Observed	Stage(s) (Spawning, Rearing, Migration)
Cutth, Steel-	5/4/79	Rearing
HEAD		

Drafted Rew 2/8c

Comments: Please provide any clarifying information. Also, please include a map of the area identifying the stream reach. This can be a copy of the map from the Anadromous Waters Atlas.

Electroshock results

Unit #45-1, 45-2

J. McCullough, G. Hopper 5/4/79

Rleed

Ron Considine, Habitat Biologist, Ketchikan

Name of Observer (please print) Bob Metzger

Date: 12/19/83 Signature: Bob Metzger

Address: USFS, Thorne Bay District

Ketchikan

CMY 2/6/80

Len Bradley
Mike Pease
Barry Lybrand
Fish & Game

Date: 5/4/79

Fish Stream Survey Report

103-90-025

Camp [illegible]

Stream Name(ID) YATUK (Upper)

Road# 5606 Station# _____ Unit# 45-1 45-2 RP# _____

Quad Map CRAIG D-4 Section _____ Chick Map 28 of 55 Section _____

Fish Present

	Yes	No
	Y	
Above Road Crossing	X	
Below Road Crossing	X	
Within Unit Boundary	X	
Below Unit Boundary	X	

Species Present/Stage of Development COHO ALEVIN AND FRY, DOLLY VARDEN AND RAINBOW JUVENILES, ADULT CUTTHROAT

Type of Fish Habitat

Salmon Spawning Area	X	sq yds Describe 70-75 %
Salmon Rearing Area	X	sq yds Describe _____
Other _____ Area _____		sq yds Describe _____

Stream Sketch or Map: Attach supplement if necessary:

Supplement

Method(s) used to determine presence of fish: shocker

YATUK CR. Date	#Fish	Approx Length	Gear	Length of Time Fished
5-3-79	(1) RAINBOW	1.5 inches	SHOCKER	30 min.
	(1) RAINBOW	3.5 inches		
	(2) RAINBOW	2.0 inches		
	(1) COHO	2.0 inches		
	(6) COHO	1.0 inches		
	(1) DOLLY VARDEN	1.5 inches		
	(1) SALMON	8.0 inches		
	(4) CUTTHROAT	8.0 inches		
	(1) CUTTHROAT	9.0 inches		

future fish habitat enhancement possible? Yes X No

If yes Describe:

THE BLOWDOWN IN THIS CREEK (Yard) SHOULD BE REMOVED TO MINIMIZE IMPACT ON EMERGING FRY. BY CAMPBELL LOGGING CO. OR BY A YACC CREW. BECAUSE OF THE HIGH PRODUCTIVITY AND SPECIES DIVERSITY OF THIS STREAM, IT SHOULD BE CONSIDERED TOP PRIORITY.

Road and Unit boundary/fish stream intersection(s)
Marked with aluminum metal tags — Yes X No

Fish stream(s) flagged with blue stripe tape — Yes X No

Stream(s) traversed-If so attach traverse notes — Yes No X

Additional parameter information necessary, — Yes No X
If so attached completed fish stream parameter
Data form

Pertinent Wildlife Information:

DEER DROPPINGS AND TRACKS

Comments: See supplements
Note proposal to add additional blowdown in this area. Yarder is temporarily inoperative. The size of the blowdown appears to be beyond the ability and # allocated for hand clean up. Logging additional area may be a feasible and reasonable trade off to get the stream cleaned - Brady - why don't we get on the ground for this soon

Survey Crew Members:

	Signature	Date
Jim McCullough	Jim McCullough	5/4/79
Glenna Hopper	Glenna Hopper	5-4-79

Report Reviewed By Mike Navy — Signature
Forester — Title within the unit
5-14-79 — Date

Recommendations: Blowdown/logging debris should be removed by the operator concurrent with yarding operations. Falling blowdown debris must be removed within 48 hrs of deposit. Operations should be timed to remove blowdown prior to return of salmon this fall. Crews are available to mark blowdown to be left if necessary. Directional falling required for removing trees along creek. Re blowdown or timber in the creek if possible the longest yard when possible. Brush roads off of for / Main Uphill when possible. Smaller trees (L 24-35') may be yarded with road wads Larger root wads may have to be left in place. IBM - yard along or fully suspend over creek

IT 45-1 AND 45-2 BLOWDOWN ROAD 5606

DESCRIPTION

YATUK CREEK IS APPROXIMATELY 8-12 FEET WIDE AND 6-18 INCHES DEEP WITH 3-4 FEET POOLS. THIS STREAM HAS ROCK / GRAVEL SUBSTRATE WITH LITTLE SAND. IT FLOWS BETWEEN UNITS 45-1 AND 45-2 AND PROVIDES EXCELLENT SALMON SPAWNING AND REARING HABITAT (70-75 S. WELL AS EXCELLENT RESIDENT FISH HABITAT. THE CREEK WAS TAGGED NORTH OF THE BRIDGE AND FLAGGI BLUE/WHITE UP TO A 3-4 FT. FALLS, ABOVE THE FALLS ONLY RESIDENT FISH WERE FOUND AND THIS WAS FLAGGED ORANGE/WHITE. SOUTH OF THE BRIDGE AND EXTENDING SOUTH APPROXIMATELY 3000' FT TO ABOVE ROAD CROSSING 5606.02 THERE IS ALOT OF BLOWDOWN CAUSING DEBRIS DAMS AND FISH BARRIERS. THE TEMPERATU OF YATUK CREEK WAS FOUND TO BE 51° F.

RECOMMENDATIONS:

ALL NEW BLOWDOWN SHOULD BE REMOVED FROM YATUK CREEK DURING SUCH A TIME AS TO MINIMIZE IMPACT ON ALEVINS AND SPAWNING SALMON. EXISTING UNIT BOUNDARYS SHOULD BE EXTENDED NORTH AND SOUTH TO INCLUDE ALL NEW BLOWDOWN IN THE STREAM. THIS SHOULD be CONSIDERED A HIGH PRIORITY PROJEC AS THIS IS A VERY PRODUCTIVE CREEK WITHIN THE


N
45-1
45-2
VATNA CREEK
9095
Temperature Sensative
CLEAR CUTS
PROPOSED CUT BLOWDOWN
EXTENDED BLOWDOWN CUT
TO DUMP


45-1
45-2
PRINCE OF WALES ISLAND
EL CAPITAN ISLAND
Craig
Kasaan
Klawock
Hollis
Thorne Bay
Naukati
Coffman Cove
Whale Pass
Kasaan Bay
Kasaan Peninsula
Kasaan Island
Klakas Inlet
Klawock Inlet
Klawock Island
Stanley
Kina Islands
Twin Islands
Dickens Island
Hecata I
Dall I
Cunningham Island
Brownson I
North Island
Kosciusko Island
Skowl Island
Sarkar Island
Tuxekan
Sea Otter Sound
Nichols Bay
Jinkis Bay
Naukati Bay
Craig D-4