Barrier

OK R. Reed Reg Sup. 3/11/85

State of Alaska
Department of Fish and Game 85-378
Public Review Nomination for Waters
Important to Anadromous Species

TS 10-9-85

☐ Addition ☒ Deletion

OK SRS 10/23/85

Name of Waterbody (if known): none

Location: West Kosiusko Island
PRINCE OF WALES ISLAND CC. PA. NAUK. TNP

Anadromous Waters Catalog Volume and Number 105-50-10060

USGS 1:63,360 Quadrangle CRAIG (D-6) (3)

or 1:250,000 (if 1:63,360 not available) _____

Species	Date(s) Observed	Stage(s) (Spawning, Rearing, Migration)
n/a		

ALASKA DEPT. OF FISH & GAME

MAR 14 1985

REGIONAL OFFICE

Comments: Please provide any clarifying information in addition to identification on Anadromous Waters Catalog Public Review Maps.

Impassable bedrock fall, see map and data

Name of Observer (please print) RON MEDEL FISHERIES TECH. BM
BOB METZGER FISHERIES BIOL.

Date: 12-20-84 Signature: Bob Metzger

THORNE BAY RANGER DISTRICT
POB(8438)
KETCHIKAN, ALASKA, 99901


105-50
10060
P
CO
SR
CO
2005
P
CH
CO
P
CH
CO
P
CH
CO
10530
10580
10140
P
CO
Point Hardscrabble
Cape Pole
Cape Pole
KOSCIUSKO ISLAND
Steppass moraine
Survey
Survey Cove
Halibut Harbor
CHANNEL
Black Rock
Cosmos Pass
Pass
Whale Head Island
Whale Head
Warren
Peak
Cabin
Cabin
Cabin
Lichen
Quartz
Berry
Skag
King
103-90
105-50

BRIDGE/CULVERT SURVEY REPORT

DATE 10-31-84 CAMP Cape Ble STREAM CATALOG NO.# 105-50-10060

ROAD NUMBER 15 RD BRIDGE/CULVERT/STREAM NUMBER 2.35 mile (see map

BRIDGE/CULVERT TYPE: Stringer FISH PASSAGE: YES — NO _____ PART. _____

WOOD/CMP LENGTH _____ WOOD/CMP HEIGHT OR DIA. _____

SPECIES PRESENT	STAGE OF DEVELOPMENT
non-sports DV	

FISH PASSAGE REQUIRED: YES — NO _____
STREAM ASSESSMENT REQUIRED: YES _____ NO — (ABOVE/BELOW)
ASSESSMENT/TRAVERSE NOTES ATTACHED: YES _____ NO —

FLOW (CFS):

ABOVE CULVERT _____
BELOW CULVERT _____
INSIDE CULVERT _____

STREAM GRADIENT: 0-1% throughout

ABOVE CULVERT _____
BELOW CULVERT _____
INSIDE CULVERT _____

PLUNGE POOL DEPTH _____ DROP FROM OUTLET _____

BRIDGE/CULVERT: DAMAGED/BLOCKED/BURIED/BAFFLED

COMMENTS: Stringer is located immediately before the 1520 "Y" on the 15 road (see map). Previously tagged incorrectly. Stream is non anadromous and is flagged green & white. Area is ponded with no gradient problems.
Note: 14 ft. bedrock face fall located 110ft below 1510 crossing

SURVEY CREW MEMBERS	SIGNATURE	TITLE	DATE
Ron Medel			
Russ Stewart			

REPORT REVIEWED BY: _____

RECOMMENDATIONS: No timing
No passage ness
Res non sports

102v


Point Hardscrabble
Scrabble
11
12
R 75 E
R 76 E
1510
5702
ROAD
15
14
13
18
15 ROAD
barrier fall
5700
Light
Halibut Harbor
WC
CAPE POLE
Cape Pole
0.30 mile crossing
2.35 mile crossing
Creek
22
23
24
19
1520
KOSCIUSKO ISL
27
26
25
30
Survey
5712
5708
33
34
35
36
1520
4.35 mile Crossing
31
346
Hali
Harbor
5
4
3
5710
2