State of Alaska
Department of Fish and Game
Nomination for Waters
Important to Anadromous Fish

ALASKA DEPT. OF FISH & GAME

OCT 13 1992

REGION II
HABITAT DIVISION

AWC Volume (SE) SC SW W AR IN USGS Quad Craig B-4

Anadromous Water Catalog Number of Waterway 103-60-10505

Name of Waterway Pump House Creek USGS name ___ Local name X

Addition ___ Deletion ___ Correction X Backup Information ___

For Office Use

Nomination # 93 050	Jana L Shea — Regional Supervisor — Date 10-9-92
Revision Year: 94	[illegible signature] — Date 8/26/92
Revision to: Atlas ___ Catalog ___ Both N/A	
Revision Code: 82	Drafted — Date

OBSERVATION INFORMATION

Species	Date(s) Observed	Spawning	Rearing	Migration	Anadromous

Provide any clarifying information, including number of fish observed, location of fish survey data, etc. Attach a copy of the fish survey data, if available. Attach a copy of a map showing location of mouth and upper points of each species, specific stream reaches identified for spawning or rearing, locations of barriers, such as falls.

Comments:

Stream as drawn is composite of two streams. Lower end belongs to stream which may well be anadromous, but becomes too steep after crossing under Port St. Nicholas Rd. Upper portion is stream which has been heavily impacted by logging above it. DOT just put in major culvert designed to pass fish. Separate streams, + shorten the upper end. One with new culvert is locally known as Pump House Cre

Name of Observer (please print) James D. Durst, Habitat Biologist

Date: 10/6/92 Signature: James D Durst

Address: ADF&G Habitat Division
P.O. Box 271, Klawock, AK 99925

Signature of Area Biologist: Jack Gustafson

HOLD TIL GET SAMPLING VERIFICATION ON PUMPHOUSE CREEK

91

FINAL

CRAIG (B-4) QUADRANGLE
ALASKA
1:63360 SERIES (TOPOGRAPHIC)



10 April (cont.)

another seepy trib or two, including one that flows well on occasion (53" gravel bedload in places) but was subsurface on inspection in places (Type C)

checking out creeks in CB-92-5:

Orange Creek

2360 S most - orange stains; nasty; 1 trap in hole midway; 3'

"orange 2" = "Miserable"

360 next creek; clear + nice; 3'
1 trap just upstream buffer

Dump Creek
Staged? [illegible]
= Pump House Creek

nice creek next; one through upper culvert by trailer court; 1 trap in first trappable hole (stream's pretty shallow but ok for fish); 1DV 1 trap by mouth

10 April (cont.)

several C ish seeps

stream w/ fry in intertidal; >8% at buffer line, so did not trap; comes out by pull-out bench w/ alder

stream at S point @ mouth Crab Creek; looks ok; float home uses for domestic water, so 2 dams by time it leaves the buffer; OK above, but buffers provide adequate protection on stream

walked to upper end Crab Bay, cataloged stream #103-60-10495 "Dipstick Creek"; new highway has perched culvert; only place above it to trap was immediately above, so placed 1 trap

pulled after ± 24 hrs. n.f.


CRAB
BAY
"Pump House Creek"
103-60-10505
Delete Upper
103-60-10510
CB-92-9
CB-92-10
ST-92-1
GY-92-2
CAPE SUSPIRO
STATE AREA FORESTER
KETCHIKAN
MAR 1 3 1992
RECEIVED