AWC Nomination
Tributary to White River near Ketchikan

Fish were trapped July 25, 2006 above and below a 48" CMP culvert on a logging road near the White River east of Ketchikan. In a pool just above the culvert (55.45953/131.57743 NAD27) I caught 2 Dolly Varden char 90 mm and 110 mm. In a pool below the culvert (55.45963/131.57729) I caught 4 coho salmon about 85 mm and 1 cutthroat trout about 130 mm. This probably a tributary to Stream #101-45-10240-2011.


Trib to #101-45-10240-2011, COr, CTr, DVr
State of Alaska - Dept. of Fish and Game - Division of Sport Fish 2006
0
1.6mi

July 25, 2006

WP34 ~~Lone stream~~ 24" pipe dry. Stream flows next to road here. Is high water pipe?

WP35 stream 48" CMP
Traps above + below in 12564
inlet @ 1500h
out @ 1700h
4 coho ~85 mm
1 cut ~130 mm
2 BV ~90 mm (P15)
14 pool ~110 mm
up ~100 mm
(P56)

WP36 18" ditch drain

WP37 18" ditch drain

WP38 24" ditch drain

CFX 0298 starts @ spur going N.

WP39 24" cross drain

WP40 Msg cross drain flow pit

CFX0151

WP41 log culvert. Back water to River. Trap in @ bridge 135pm

WP42 Foot bridge over White River
(P9-10) 8-9?

CFX0170

WP43 Bridge over cut stream?
(P10) Gap in stringer, Seed falling in stream on upstream side
Neck connection (Bull rail)
Bridge should be replaced
Not a big problem if little road use. Log isn't cabled in + slid

WP44 18" CMP ~~RT~~ drains ~~seep~~ spring next to pit

WP45 60" pipe on stream
Trap @ ~~of~~ outlet pool 1400h
Cascades upstream too shallow to trap, but could be passable for fish @ higher flows.
(P11) = inlet (P12) outlet trap

WP46 MS6 structure. Flow off hill runs along road. (P12)

CFX0172

WP47 36" CMP stream.
~~Very perched @~~ output @ steep gradient
(P13) Natural block ~50% grad
NOT fish