101-29-35 101-29-10350

Larson, Jackinsky
11-11-76

3800' to LTZ

Logs in stream

Muddy bottom

Stream small 3' wide - 2" deep

End of usable area

Trib.

2' high bank

Dead eggs

1-2"gravel

6' wide

Swift water, undercut banks

60% ASA - 7' wide

Sand to 2" gravel

Shallow pools to sides

Red flagging on bushes

Blue clay outcrop

50% ASA - 8' wide

50% pools, mossy banks

POOL

ASA 30% - 8' wide

POOL

Stream very small

395 fish bones on bank of creek (about 90% pink)

Red flagging on bushes

Banks silty mossy, overhanging

Tree roots in creek

Very mossy

ASA 30% - 8' wide

Bedrock bank - red flagging on brush.

Dirt & silt bank

Pool

Trib.

2' falls

ASA 20% - 8' wide

Bedrock bottom for short distance

Trib.

ASA 50% - 10'wide

50% pools

Deer tracks

WEATHER: Overcast, 49°F.

SLOPES: Gentle to moderate

Trib.

Slow riffle

Seagull remains on log

Many fish bones on bank

Gravel 1-8"

Fine substrate

Banks mossy, overhanging

ASA 50% - 8' wide

Dippers in creek

ASA 50% 10' wide

50% pools

Seagull remains

Small gravel 1"

Mossy banks

POOL

Bird feathers, remains

POOL

ASA 65% - 10' wide

Red flagging on brush

20% rubble

50% ASA -30' wide

Bedrock

About 4 cfs

pH 7.5, 44°F.

Light brown/clear

Logging debris

Blue clay

Boat moored in channel (hunters)

Small trib.

Blue clay banks

POOL

Second growth timber

Spruce/hemlock

Aspen along shore

ITZ (200'x10'x70%)

Bedrock