PEAK ESCAPEMENT RECORD

103-70=45 E. shore Noyes Island 1/4 mile S. of stream 78

DATE	PINK	CHUM	OTHER SPECIES	REMARKS
10/9/45	8,000	400		Good - 3,000 at mouth
No other recorded data				


2625'
(800 m)
Hemlock, cedar, spruce
Banks stable
Devils club
Small stream with brown tinted water, bedrock bottom with small falls and pools with coho fry.
5'
(1.5m) bedrock falls.
Bedrock with
(1m) cascade 3'
Blueberry
Limestone
Limestone bedrock
700m 2297'
Stagnant pond looks like small limestone sinkhole.
Limestone
Alder
(2.5m) falls
8'
Not a barrier, but less fry seen.
(.3m) wide 1'
Skunk cabbage
(15m) wide 49'
Gravel 2-10cm
600m
Large ferns 1968'
skunk cabbage
Pool
4m x
30m x
10% ASA
Tributary
(.3m) wide 1'
Gravel
5-20cm
100m x
3m x
90% ASA
Hemlock, cedar, spruce
(.2m) cascade .6')
Alder
500m 1640'
(.2m) cascade .6'
Low stable banks
Devils club, blueberry
Hemlock, spruce, cedar
Gravel (5-20 cm) 2-8"
(8m) wide 26'
Alder, blueberry
100m x 8m x
95% ASA
Spruce, hemlock, some cedar
400m 1312'
Continues with similar conditions.
Alder
Bedrock
Hemlock, spruce, cedar.
Limestone bedrock exposed in places.
1100m
3609'
Bedrock
Pool. Good spawning with pools for rearing.
2m x 200m x 80%
2-4"
Gravel (5-10cm) average.
Blueberry
Easy to walk
Bedrock
Blueberry
Hemlock, cedar
3281
(1000 m)
Skunk cabbage
Gravel (2-10cm)
1-4"
Pool with coho fry.
Hemlock, spruce cedar
(900m)
2953
2m x 200m x 50% ASA
(2m) wide 7'
Pool with coho fry.
(2m) wide 7'
Bedrock
Moderate grade
Bedrock
2625'
(800m)