CC Fred. Zeigler
Pete Mondich
Fish & Game.

Date: 5 OCTOBER 1978

Fish Stream Survey Report

Camp THORNE BAY/NORTH THORNE RIVER Stream Name(ID) EAST FORK OF NORTH THORNE RIVER 102-70-53

Road# 5052 Station# _____ Unit# _____ RP# _____

Quad Map ECHO SPUR Section _____ Chick Map 33 Section 22 & 15

	Yes	No
Fish Present	✓	
Above Road Crossing	✓	
Below Road Crossing	✓	
Within Unit Boundary	✓	
Below Unit Boundary	✓	

Species Present/Stage of Development COHO (ADULT/SMOLT/FRY)
DOLLY VARDEN (ADULT/FRY)

Type of Fish Habitat

Salmon Spawning Area 2½ MILES ~~sq-yds~~ Describe EXCELLENT
Salmon Rearing Area _____ ~~sq-yds~~ Describe EXCELLENT
Other _____ Area _____ ~~sq-yds~~ Describe EXCELLENT

Stream Sketch or Map: Attach supplement if necessary:
SEE ATTACHED SUPPLEMENT

Method(s) used to determine presence of fish:

Date	#Fish	Approx Length	Gear	Length of Time Fished
5 OCT 78	25 - COHO ADULTS (BOTH BRANCHES OF EAST FORK)	24"	SHOCKER + OBSERVATION	15 MIN
↓	SEVERAL COHO FRY & SMOLT	1½" TO 3½"	"	40 MIN

Is future fish habitat enhancement possible? Yes _____ No ✓
If yes Describe:

Road and Unit boundary/fish stream intersection(s)
Marked with aluminum metal tags Yes _____ No ✓
Fish stream(s) flagged with blue stripe tape Yes _____ No ✓
Stream(s) traversed-If so attach traverse notes Yes _____ No ✓
Additional parameter information necessary, Yes _____ No ✓
If so attached completed fish stream parameter Data form

Pertinent Wildlife Information:
FRESH BEAR & DEER TRACKS & SIGN OBSERVED
MINK OR MARTEN SIGN

*(2ND BRIDGE CROSSINGS HAVE BEEN PULLED & ARE IN PORTION OF ECHO SPUR THAT HAS BEEN PUT TO BED.)

Comments: OBSERVED ADULT & JUVENILE COHO AT SITES OF 2ND* BRIDGE CROSSINGS INDICATE NO ANADROMOUS FISH BARRIER BETWEEN 1ST (ON ROAD #5051.02) AND 2ND* BRIDGE CROSSINGS OF EAST FORK OF NORTH THORNE RIVER
RIGHT BRANCH OF EAST FORK: SALMON HABITAT CONTINUES ABOVE 2ND BRIDGE SITE ≈ 1/2 MILE.
LEFT BRANCH OF EAST FORK: SALMON HABITAT CONTINUES ABOVE 2ND BRIDGE SITE ≈ 1,000 FEET

Survey Crew Members:	Signature	Date
LAURA A. HOLL	Laura A Holl	6 OCT 1978
JIM GEUBER	Jim Geuber	

Report Reviewed By Michael E. Nary (Signature) Forester (Title) 10-8-78 (Date)

Recommendations:

Recommend units on East fork be surveyed for remedial clean up work


TRUE NORTH
2ND BRIDGE CROSSINGS
UNIT 8-7
145.7 AC.
UNIT 8-8
197.4 AC.
EAST FORK OF NORTH THORNE RIVER
FLOW
UNIT 8-9
89.5 AC
5051.02 ROAD
FLOW
EAST FORK OF NORTH THORNE RIVER
5052 ROAD (ECHO SPUR)
1ST BRIDGE CROSSING
FLOW
UNIT 8-10
140.0 AC
LEDGEND
UNIT BOUNDARY
SPECIFIED ROAD
DIRECTION OF RIVER FLOW
MAP TRACED FROM CHICKERING MAP 33