

Division of Commercial Fisheries  
Sam Rabung, Director

Cordova Area Office  
401 Railroad Ave.  
Cordova, AK 99574



Alaska Department of Fish and Game  
Doug Vincent-Lang, Commissioner

PO Box 115526  
Juneau, AK 99811-5526  
www.adfg.alaska.gov

**Advisory Announcement**  
*For Immediate Release: July 11, 2021*

**CONTACT: Jeremy Botz and Heather Scannell**  
**Finfish Area Management Biologists**  
**(907) 424-3212**

**Prince William Sound Salmon Fishery Announcement #28**

**SEINE FISHERIES:** This news release is being distributed at the request of the U.S. Coast Guard.



Captain of the Port  
United States Coast Guard  
Prince William Sound Alaska \

PO Box 486  
105 Clifton Drive  
Valdez, AK 99686  
Phone: 907-835-7210  
Fax: 907-428-7207

1. **PURPOSE:** This navigation advisory is provided to remind all mariners the importance of following the requirements for operating a vessel upon the navigable waters of Prince William Sound. Additionally, it outlines specific navigational safety concerns and risk mitigation measures available for vessels operating in the Valdez Narrows.
2. **DISCUSSION:** In December 2017, Marine Safety Unit Valdez determined there has been a steady increase in the number of near-miss collisions between tank vessels and fishing vessels in Port Valdez and Prince William Sound. This increased risk of vessel collisions is avoidable by adhering to the requirements in this advisory and, if not corrected, could lead to injury of personnel, damage to equipment, and harm to the environment. This situation could be aggravated by the increased vessel traffic due to the current transition taking place in companies providing escort towing for TAPS tankers. This change requires training of vessels and crew with exercises in and around the Port of Valdez and Prince William Sound.
  - a. **Responsibilities Between Vessels:**
    - i. Every vessel shall at all times maintain a proper look-out by sight and hearing by all available means appropriate in the prevailing circumstances and conditions so as to make a full appraisal of the situation and thus reduce the risk of collision, per Rule 5 of the International Navigation Rules.
    - ii. Any vessel less than 65 feet, or a vessel engaged in fishing shall not impede the passage of a vessel which can safely navigate only within a narrow channel or fairway (e.g. Valdez Narrows), per Rule 9 of the International Navigation Rules.
    - iii. A vessel crossing a traffic separation scheme shall cross on a heading as nearly as practicable at right

angles to the general direction of traffic flow, per Rule 10 of the International Navigation Rules.

- iv. A vessel engaged in fishing within the traffic separation scheme, shall not impede the passage of any vessel following a traffic lane, per Rule 10 of the International Navigation Rules.
- v. All vessels shall adhere to Rule 18 of the International Navigation Rules, which outlines the navigational responsibilities between vessels underway. In particular, a power-driven vessel shall keep out of the way of a vessel engaged in fishing (except where Rules 9, 10 and 13 is applicable).

**b. Communications:**

- i. 33 CFR 26.03 requires VTS Users to carry a radiotelephone on board at all times.
- ii. 33 CFR 161.12 requires VTS Users to maintain a listening watch on VHF Channel 13 and must respond promptly when hailed.
- iii. 33 CFR 161.12 states VTS Users shall report to the VTC whenever they are unable to comply with any VTS regulation. (e.g. radio malfunction).

**c. Security Zones in Prince William Sound:**

- i. 33 CFR 165.1710 states a security zone exists around all waters 200 yards either side of a Tanker's optimal track line in the Valdez Narrows.
- ii. 33 CFR 165.1710 establishes a security zone within Buoy Alpha and Buoy Bravo approximately 0.8 NM from the Trans-Alaska Pipeline Valdez Terminal.
- iii. No vessel or person may enter or remain in a security zone without the permission of the Captain of the Port.

**d. Violation of rules and regulations:**

- i. A violation for failing to carry a radiotelephone can start out at \$100 and go up to \$650.
- ii. A violation for failing to maintain a listening watch on Ch. 13 and 16, failing to respond when hailed or failing to report to the VTC the inability to comply with 33CFR 161.12 requirements can result in a \$1,000 and up to \$40,000 fine.
- iii. Failing to follow Rule 9 or 10 of the International Navigation rules can result in a fine starting at \$5,000 and can go up to 1 year of imprisonment for gross negligent operations.
- iv. A security zone incursion can result in a violation fine starting at \$2,000 and going up to \$40,000.



**There are three security zones in the Port of Valdez:**

1. **Alyeska Marine Terminal Security Zone** – Fixed Zone. Marked on the North corners by two yellow buoys 1.7 miles apart and 0.8 miles.
2. **Tank Vessel Moving Security Zone** – Moving Zone. 200 yards around any tank vessels in Prince William Sound.
3. **Valdez Narrows Security Zone** – Fixed Zone. 200 yards on either side of the Valdez Narrows Optimum Trackline. Active only when a tank vessel is in the Security Zone. Vessels must stand clear whenever a tank vessel enters the Valdez Narrows.

