



State of Alaska  
Department of Fish and Game  
Division of Sport Fish

Fish Survey  
Nomination Form  
Anadromous Waters Catalog

E

Region: Southeast

USGS Quad: Ketchikan B-6

Anadromous Waters Catalog Number of Waterway: 101-47-10150-2039

Name of Waterway: Unnamed

Addition

Deletion

For Office Use

Correction

USGS Name

Local Name

Backup Information

Nomination #	150314	Fisheries Scientist	Date
Revision Year:	2016	Habitat Operations Manager	Date
Revision to: Atlas	Catalog	AWC Project Biologist	13 July 15
Both		GIS Analyst	Date
Revision Code:	F-1		

Site Information Survey: SEA13WLR07 Date Observed: 08/11/2013 Legal Desc.: C074S090E23 Latitude Longitude Datum  
Site: 10103165 55.43204 -131.68687

Observation Information

Life History:

Species\LifeStage: coho salmon juvenile

Sampling Method (No. of fish): B (9)

Key To Sample Events

Sample ID: (A) Sample Gear: Minnow Trap  
Sample ID: (B) Sample Gear: Minnow Trap

*coho salmon juv previously documented*

**Additional Comments:** This nomination provides backup information to support fish presence for juvenile coho for 101-47-10150-2039. This information was collected as part of the ADF&G Fish Passage Project. Upstream trap was set 22' from culvert and produced no fish. Downstream trap was located 24' from culvert and produced 9 juvenile coho. Downstream creek passes through 2 more culverts on Forest Service campground roads. Downstream USFS road crossing placards indicate stream has Dolly Varden, Cutthroat Trout, Coho, Pink and Sockeye salmon. There are three concrete culverts about 175 feet upstream under another forest service road. Nice habitat upstream and downstream of culvert. Pools mostly controlled by boulders and a little large woody debris in system.

Name of Observer: Mark Eisenman, Habitat Biologist

Phone: (907) 267-2891 Date Printed: 6/10/2015

Signature: \_\_\_\_\_


Address: Alaska Department of Fish and Game, Sport Fish - Anchorage  
333 Raspberry Rd  
Anchorage, AK 99518

ALASKA DEPT. OF  
FISH & GAME


JUL 10 2015

This certifies that in my best professional judgment and belief the above information is evidence that this waterbody should be included in or deleted from the Anadromous Waters Catalog

Signature of Area Biologist: \_\_\_\_\_ Date: \_\_\_\_\_



IMG7943.jpg  
Site ID



IMG7944.jpg  
Road



IMG7945.jpg  
From road looking u/s



IMG7946.jpg  
From road looking d/s



IMG7947.jpg  
Outlet



IMG7948.jpg  
Outlet



IMGP7949.jpg  
Outlet




IMGP7950.jpg  
Downstream from outlet



IMGP7951.jpg  
Downstream culvert through  
forest service campground



IMGP7952.jpg  
 Downstream looking upstream  
 at outlet



IMGP7953.jpg  
 Downstream FS stream  
 crossing placard




IMGP7954.jpg  
 In outlet

FOREST SERVICE STREAM CROSSING		
CT	Road:	800025
DOV	Milepost:	0.109
SH	Date:	6/25/02
SS	Crew (1):	9 CROSS
CS	Crew (2):	9 AULL
PS	Remarks:	REMEASURE
RS		
		Stream Class
		I <input checked="" type="radio"/>
		II <input type="radio"/>
		III <input type="radio"/>
		IV <input type="radio"/>

J. L. DARLING CORP.  
 (253) 522-5000



IMGP7955.jpg  
In culvert



IMGP7956.jpg  
Looking upstream from inlet




IMGP7957.jpg  
In inlet



IMGP7958.jpg  
Inlet




IMGP7959.jpg  
Inlet




IMGP7960.jpg  
Inlet



IMGP7961.jpg  
Upstream habitat




IMGP7962.jpg  
Upstream substrate




IMGP7963.jpg  
Upstream culverts through  
forest service road (concrete  
culverts)



IMGP7964.jpg  
Downstream fish photos, bucket



IMGP7965.jpg  
Downstream fish photos, coho



IMGP7966.jpg  
Downstream fish photos, coho





