

LATITUDE: 55 21' 16"
 LONGITUDE: 131 41' 25"
 TIDE AT TIME OF SURVEY: Half flood
 WEATHER: Broken clouds, fair, 50 F
 TREES: Mixed deciduous shrubs.
 MAP NO: Ketchikan B-6
 WATER SUPPLY: Runoff
 LENGTH: 1 mile
 DRAINAGE: 1 sq. mile

101-47-18 101-47-01
 6-11-76
 Jackinsky

SUBURBAN HOUSING AREA

Large numbers of coho fry noted in the past.

Very small tributary - barrier falls over logs 4'.

About 3/8 mile from saltwater.
 Creek flows in narrow ravine.
 City sewer line bridges ravine.
 Garbage and dirt slide

Logs, stumps, brush obscure creek from here up, Creek periodically disappears then coalesces.

Pools & riffles.

Much garbage in creek.

Trash and logs dam stream.

Pool
 Pool

No fry observed.


Overhanging bushes from here up, difficult walking at times.

Pool, 1'Dx10'x5'.

Very limited spawning and rearing.

Very little water in creek. Much algae, some moss on rocks. Bottom gravel to 4", dirt, silt.

Creek flows through subterranean culvert here to saltwater (100 yds) possible barrier.



Rip-rap with gravel fill.

Culvert empties below high tide level.

