Fish & Game

Date: 6-15-78

Fish Stream Survey Report

Camp Thorne Bay Stream Name(ID) 102-70-058

Road# Shaheen B Spur ~~Station#~~ EXISTING ROAD AND extension Unit# _____ RP# _____

Quad Map _____ Section _____ Chick Map _____ Section _____

Fish Present Yes _____ No X

	Yes	No
Above Road Crossing		
Below Road Crossing		
Within Unit Boundary		
Below Unit Boundary		

Species Present/Stage of Development No FISH

Type of Fish Habitat

Salmon Spawning Area _____ sq yds Describe _____

Salmon Rearing Area _____ sq yds Describe _____

Other _____ Area _____ sq yds Describe _____

Stream Sketch or Map: Attach supplement if necessary:

Method(s) used to determine presence of fish:

Date	#Fish	Approx Length	Gear	Length of Time Fished

Is future fish habitat enhancement possible? Yes _____ No X
If yes Describe:

Road and Unit boundary/fish stream intersection(s)
Marked with aluminum metal tags Yes _____ No X
Fish stream(s) flagged with blue stripe tape Yes _____ No X
Stream(s) traversed-If so attach traverse notes Yes _____ No X
Additional parameter information necessary, Yes _____ No X
If so attached completed fish stream parameter
Data form

Pertinent Wildlife Information:

Comments: We walked the existing road and determined that the slope of the present spur and proposed extension is too large to provide fish habitat. No drainages were found.

Survey Crew Members: Signature Date

Cathy L. Rose 6-15-78

Report Reviewed By Mike Novy (Signature) Forester (Title) 6-19-78 (Date)

Recommendations: