



11 Mile Creek  
 103-70-11  
 6-10-77  
 Larson 103-70-10110

Tide - low  
 Weather - overcast  
 Air 58°F  
 Water - lt. brown/clear  
 Water temp 52°  
 pH - 7.0  
 Flow: approx. 15 cfs  
 Fair rearing for coho



103-70-10110

Name: 11 MILE CREEK Catalog No: 103-70-11  
Latitude: 55° 35' 08" 07" Former Stream No: WC 47, Previous #38  
Longitude: 133° 16' 30" 31"  
Geodetic Map No: Craig C-4 Work Area: Ketchikan  
Location: Prince of Wales Is., north shore Watershed Length: 4.5 mi (main fork)  
of San Christoval Channel. 1.1 miles east Drainage Area: 5.6 sq. miles  
of the north tip of Rosary Is. Water Supply Type: runoff from low forested  
hills and scattered muskegs, 2 small lakes  
Trails & Survey Routes: streambed easily walked for distance surveyed.

Aerial Survey Notes: the intertidal and mouth portions easily observed from air.

Anchorage: near the mouth in good weather or in Cruz Cove on San Fernando Is.

Tide Stage when Surveyed: low

### RESOURCES

COMMERCIAL FISHERIES (species, escapement, timing, spawning area):  
pinks, chum and coho  
fair rearing for coho

Spawning area: 1950 meters<sup>2</sup> (2800'x25'x30%ASA)  
Schooling Areas: at the mouth and in a large pool near the high tide mark.

Spawning Areas: in the upper intertidal area and scattered sections upstream.

SHELLFISH POTENTIAL: only a small gravel flat at the mouth.

SPORT FISHERIES: low potential due to small size and lack of lakes, fair rearing  
for coho.

LAND USE (history, present, proposed): unknown; presently in a natural state.

REHABILITATION POTENTIAL: none needed.

SOILS: generally stable; several braided areas and cutbanks upstream (see map).

GAME RESOURCES (species, use, habitat): reported to be a good fur-bearer area;  
deer, bear, and wolves in the area.

# PEAK ESCAPEMENT RECORD

11 Mile Creek 103-70-11 (San Christoval Channel)

DATE	PINK	CHUM	OTHER SPECIES	REMARKS
9/3/74	2,500			
8/17/75	7,500			
8/23/76	5,000			
8/16/77	7,000			