

HC 60 Box 2008 Haines, Alaska 99827 info@takshanuk.org TAKSHANUK.ORG (907) 766 - 3542

Trip Report: Sawmill Creek Tributary - Comstock Culvert

Anadromous Stream #: 115-32-10300-2002-3013-4013Permit: SF2023-115Date: 10/17/2023Technicians: Stacie Evans, Jeremy Taylor# Minnow Traps: 8Trapping Duration: 20hrsSpecies and life stage: CTr, COsLocation:



Meridian	Township	Range	Section
Copper River	30 South	59 East	27

Trap Locations							
	Latitude	Longitude		Latitude	Longitude		
Trap #1	59.240792	-135.463874	Trap #5	59.24043	-135.464183		
Trap #2	59.240554	-135.463882	Trap #6	59.240324	-135.464362		
Trap #3	59.240382	-135.46396	Trap #7	59.240143	-135.464292		
Trap #4	59.24052	-135.464113	Trap #8	59.240077	-135.464116		

Trap Results							
	Species	Fork Length		Species	Fork Length		
		(mm)			(mm)		
Trap #1	None	-	Trap #5	Cutthroat	150		
Trap #2	Cutthroat	130	Trap #5	Cutthroat	135		
Trap #2	Cutthroat	90	Trap #5	Cutthroat	115		
Trap #2	Cutthroat	75	Trap #5	Cutthroat	125		
Trap #3	Cutthroat	125	Trap #5	Cutthroat	85		
Trap #3	Cutthroat	80	Trap #6	Cutthroat	105		
Trap #3	Cutthroat	105	Trap #6	Cutthroat	75		
Trap #3	Cutthroat	100	Trap #7	Cutthroat	95		
Trap #4	Cutthroat	75	Trap #8	Cutthroat	125		
Trap #5	Cutthroat	110					



Adult coho observed on 10/16/2023 at 59.240685, -135.463885 (above) and on 10/13/2023 at 59.241445, -135.463190 (below).

Notes: A culvert was replaced in this unnamed tributary of Sawmill Creek to improve fish passage in August 2017. Trapping was conducted to monitor efficacy of this restoration project. Traps #1-5 were set upstream of the culvert on 10/16/2023, and traps #6-8 were set downstream. Juvenile cutthroat were captured in all traps except for trap #1. Adult spawning coho were observed upstream of the trapping site on 10/13/2023, and between traps #1 and 2 on 10/16/2023.

Recommendations: Add spawning coho to 115-32-10300-2002-3013-4013 of the Anadromous Waters Catalog with an upstream extent of 59.241445, -135.463190.