Metsker

Lake/Stream Birch Lake; Location Mile 307 Richardson Hwy.

Lake Analysis

Remarks:

Weather was rainy and cloudy. Stream at hatchery site was 61° F. Spring located west of hatchery source was 45° F Temp. 12.4 to 9 was 58° - 60° F.